

# Common Electrical Work Myths



## MYTH #1 — Your work is not energized

**FACT:** Most electrical work is done while the equipment is energized, exposing workers to electrical shock and arc flash hazards. Many workers mistakenly believe that they do not need arc rated (AR) personal protective equipment (PPE) because they don't perform energized work.

Electrical equipment and circuits are either **energized** **OR** they are **locked-out/tagged-out** for maintenance. "Deenergizing" is not the same as lockout/tagout, and most tasks where lockout/tagout has not been applied to equipment would be considered energized work.

It is crucial to understand that deenergizing without locking/tagging out **does not** eliminate the electrical shock and arc flash hazards.

## MYTH #2 — My work is justified, so it's electrically safe

**FACT:** Justified energized work refers to specific situations where working on or near energized electrical equipment is deemed necessary and "justified" under certain conditions.

It may not be feasible or practical to deenergize equipment for maintenance or other tasks (such as interrupting power to a hospital).

Even when work is considered "justified," ***strict safety measures must be implemented and followed*** to minimize the risks associated with electrical hazards.

---

**For more information:**



**[www.osha.gov](http://www.osha.gov) (800) 321-OSHA (6742)**