

# Six Ways to Stay Safe When Working in Marine Terminal Mechanic Shops

**1** Ensure there is adequate lighting and ventilated work areas.



**2** Keep walking and working surfaces clear and dry to prevent slips, trips, and falls.



**3** Inspect tools, airline compressors, and equipment prior to use or operation.



**4** Turn off, de-energize, and lockout and tagout all power sources before servicing equipment.



**5** Follow safety requirements for flammable and combustible substances before performing hot work (see 29 CFR 1917.152).



**6** Chock or brace wheels before servicing equipment. Never work under equipment that is not appropriately secured.

